

ID No. 00222	Produ	ct/Process	s Change Notification	on	Date 28.01.2014
Product P	H8-P Re	I. 3			
Ordering Code L:	30960N1	910A300		***************************************	
[Part Part P	······	Vo. changes	: 🗌 Yes 🔀 No		
N	New Ordering Code:				
Reason of Change:					
☐ Technical requirement☐ Customer requirement☐ Quality improvement			 ☐ Change of production process/logistical changes ☐ Location of production moved ☐ Other: additional production site 		
Description of change:		Gemalto M2M will introduce a 2 nd source flash. This measure will secure the supply of our products. The 2 nd source flash is mechanically and electrically compatible to the current single source flash.			
		The existing a	approvals of applications are	not aff	ected.
		configuration Corrected F Improve RS 115200 bau Resolved a network lose Resolved a call that doe DTMF adde SIM more to	> 17 to AT command AT^CG on of the WWAN interface with RS232 driver to unconditional S232 driver to robustly work and an AT interpreter's task problems blocking AT Interface issues not match bearer capabilitied with increased detection rapplement designed	lly wor the interior at interior am whi when a ies ate	MI commands k without flow control face speeds lower than ch caused temporary auto answer accepts a
		The new appl	ication revision string is ARN	=01.00	01.07.
		These change	es related to applications are	not ap	proval relevant.
Scheduled date of introdu (cw/year):	ntroduction Introduction to		production: Mid of Apr 2014		
Timing note:		Provision of u	pdated SW for test: cw 05/20)14	
-			sample: cw 09/2014	•	
		_			
Quality assurance measu	rements:		ion fulfills all internal test requested		ents according to our

pcn_00222_ph8_p_rel3.docx



Product Lifecycle Manager/Name: Signature:	Ivonne Krüger Juonne Milig
VP Quality Management/Name:	Jörg Erdmann
Signature:	. Or chuceun

Attachments: